

Direct supervision of apprentices

Electrical work licence holder must be able to:



be present



communicate



provide instruction & demonstration



monitor & provide guidance



check work complies with legislation

1:1

1 licence holder to 1 apprentice

General supervision of apprentices

Level 1 - General Supervision

Licence holder must: **be present**

While work is being performed:

- provide instruction & direction
- **monitor & provide advice & guidance;**
- check that work complies with legislation

1:3

1 licence holder to no more than 3 apprentices

Level 2 - General Supervision

Licence holder must: visit the apprentice

Before work is performed:

- **provide instruction & direction**

While work is being performed:


- provide advice & guidance;
- **check that work complies with legislation**

1:5

1 licence holder to no more than 5 apprentices



Scan the QR code
Find out more on the
NT WorkSafe webpage
worksafe.nt.gov.au/forms-and-resources/bulletins/supervision-of-electrical-apprentices



When electrical work is completed by apprentice, licence holder must check and test the work to ensure the work is safe from electrical risk and complies with the legislation.